

GHS Information Is For Concentrated Product.

## WEN WENMIX #2 CLEAR OUTLOOK FLCGGGBXWEN-WM2

Flammable liquid and vapor





Warning

Causes serious eye irritation
Keep away from heat/sparks/open flames/hot surfaces.—
No smoking. Keep container tightly closed. Ground/bond container and receiving equipment. Use explosion-proof electrical/ventilating/lightling/equipment. Use only non-sparking tools. Take precautionary measures against static discharge. Wear protective gloves/protective clothing/eye protection/face protection.
Store in a well-ventilated place. Keep cool.
Dispose of contents/container to an approved waste disposal plant.


#### First Aid

First Aid Specific Treatment (See Section 4 on the SDS). IF IN EVES: Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing. If eye irritation persists: Get medical advice/attention. IF ON SKIN (or hair): Remove/Take off immediately all contaminated clothing. Rinse skin with water/shower. IF INHALED: Remove victim to fresh air and keep at rest in a position comfortable for breathing. IF SWALLOWED: Rinse mouth. DO NOT induce vomiting. Drink plenty of water. In case of fire: Use CO2, dry chemical, or foam for extinction.

24.9 % VOC

Walter E. Nelson, Company 5937 North Cutter Circle Portland, OR 97217 Phone (503) 285-3037 customerservice @ walteren

L2WENMIX2



#### GHS Information Is For Concentrated Product.

# WEN WENMIX #2 CLEAR OUTLOOK FLCGGGBXWEN-WM2

Flammable liquid and vapor





Warning

Causes serious eye irritation
Keep away from heat/sparks/open flames/hot surfaces.—
No smoking. Keep container tightly closed. Ground/bond
container and receiving equipment. Use explosion-proof
electrical/ventilating/lighting/equipment. Use only non-sparking
tools. Take precautionary measures against static discharge.
Wear protective gloves/protective clothing/eye protection/face
protection. rvear protective gloves/protective clothing/eye protection/face protection.

Store in a well-ventilated place. Keep cool.

Dispose of contents/container to an approved waste disposal plant.


#### First Aid

First Aid
Specific Treatment (See Section 4 on the SDS).
If IN EYES: Rinse cautiously with water for several minutes.
Remove contact lenses, if present and easy to do. Continue
rinsing. If eye irritation persists: Get medical advice/attention.
IF ON SKIN (or hair): Remove/Take off immediately all
contaminated clothing. Rinse skin with water/shower. IF
INHALED: Remove victim to fresh air and keep at rest in a
position comfortable for breathing. IF SWALLOWED: Rinse
mouth. DO NOT induce vorniting. Drink plenty of water.
In case of fire: Use CO2, dry chemical, or foam for extinction.

24.9 % VOC

Walter E. Nelson, Company 5937 North Cutter Circle Portland, OR 97217 Phone (503) 285-3037 customerservice@walterene

L2WENMIX2



WALTER E. NELSON COMPANY

### GHS Information Is For Concentrated Product.

# WEN WENMIX #2 CLEAR OUTLOOK FLCGGGBXWEN-WM2 Flammable liquid and vapor





Warning

Causes serious eye irritation.
Keep away from heal/sparks/open flames/hot surfaces.—
No smoking. Keep container tightly closed. Ground/bond container and receiving equipment. Use explosion-proof electrical/ventilating/lighting/equipment. Use only non-sparking tools. Take precautionary measures against static discharge. Wear protective gloves/protective clothing/eye protection/face protection. read protective gloves/protective clouling-type protection.

Store in a well-ventilated place. Keep cool.

Dispose of contents/container to an approved waste disposal plant.

First Aid
Specific Treatment (See Section 4 on the SDS).

If IN EYES: Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing, If eye irritation persists: Get medical advice/attention.

IF ON SKIN (or hair): Remove/Take off immediately all contaminated clothing. Rinse skin with water/shower. IF INHALED: Remove victim to fresh air and keep at rest in a position comfortable for breathing. IF SWALLOWED: Rinse mouth. DO NOT induce vomiting. Drink plenty of water.

In case of fire: Use CO2, dry chemical, or foam for extinction.

24.9 % VOC

Walter E. Nelson, Company 5937 North Cutter Circle Portland, OR 97217 Phone (503) 285-3037